

<p><i>CADQUEST</i> Incorporated</p> <p>Toll Free 888.922.5270</p>	<p>Pro/ENGINEER and Pro/INTRALINK Textbooks</p>
---	--

Tip of the Week

November 13, 2006

Title: Small surface configuration option.

Release: Wildfire 2.0 and Wildfire 3.0

Module: Part and assembly modules.

Tip: There is a configuration option that can save you a few mouse clicks if you create models with small surfaces. I have always used the **Model Display** dialog box to turn on the display of small surfaces (when the model is shaded). I recently found this configuration option, which will keep small shaded surfaces visible all the time.

```
skip_small_surfaces no
```

- Pick **Tools, Options**
- Enter < skip_small_surfaces > and choose *No* for the value
- Pick Add/Change, Apply
- Pick Close in the **Options** dialog box

This configuration option keeps small surfaces visible

