



## Tip of the Week

October 23, 2006

**Title:** Spin configuration options.

**Release:** Wildfire 2.0 and Wildfire 3.0

**Module:** Part and assembly modules.

**Tip:** There are two configuration options that can help visualize the model while spinning.

spin\_with\_part\_entities    Allows datum planes to be displayed when spinning.

spin\_with\_silhouettes    Allows silhouette edges to be displayed when spinning.

- Pick **Tools, Options**
- Enter < spin\_with\_part\_entities > and choose Yes for the value
- Pick **Add/Change, Apply**
- Enter < spin\_with\_silhouettes > and choose Yes for the value
- Pick **Add/Change, Apply**
- Pick **Close** in the **Options** dialog box